

Part 573 Safety Recall Report**14V-595**

Manufacturer Name : Elkhart Coach
Submission Date : SEP 24,2014
NHTSA Recall No. : 14V-595
Manufacturer Recall No. : NR

**Manufacturer Information :**

Manufacturer Name : Elkhart Coach
 Address : 52807 Country Road 7
 Elkhart IN 46514
 Company phone : 574-264-5179

Population :

Number of potentially involved : 437
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2006-2014 Ford E350 & E450

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This recall has to do with lift platforms that were put in our vehicles.

Production Dates : JAN 01, 2006 - MAY 01, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : Per Ricon Corporation Part 573 defect and Noncompliance Report 14E-041, under certain conditions, the platform included on the subject S-series wheelcahir lifts can exhibit cracking of the platform pivot plate while in the stowed position.

Description of the Safety Risk : Per Ricon Corporation Part 573 defect and Noncompliance Report 14E-04; If left unchecked, can propogate to the point where seperation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator. It is possible for the platform to lean against the doors and fall out of the vehicle.

Description of the Cause : no cause was given by Ricon Coporation.

Identification of Any Warning that can Occur : Wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position.

Supplier Identification :**Component Manufacturer**

Name : Ricon Corporation, A Wabtec Subsidiary.

Address : 1135 Aviation Place

San Fernando CA 91340

Country : US

Chronology :

Not provided by Ricon.

Description of Remedy :

Description of Remedy Program : Per Ricon Corporation Part 573 defect and Noncompliance Report 14E-041
Ricon will provide a field modification and all materials need to midigate this recall at no charge. It will be the responsibility of the lift owners to execute the mitigation.

How Remedy Component Differs from Recalled Component : Not provided by Ricon

Identify How/When Recall Condition was Corrected in Production : Not provided by Ricon

Recall Schedule :

Description of Recall Schedule : October 01, 2014 - December 31, 2014

Planned Dealer Notification Date : OCT 01, 2014 - DEC 31, 2014

Planned Owner Notification Date : OCT 01, 2014 - DEC 31, 2014

* NR - Not Reported