

Part 573 Safety Recall Report**14V-613****Manufacturer Name :** Honda (American Honda Motor Co.)**Submission Date :** SEP 29,2014**NHTSA Recall No. :** 14V-613**Manufacturer Recall No. :** JK6**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 310-783-2000

Population :

Number of potentially involved : 189

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 ACURA TLX AWD

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

Production Dates : AUG 26, 2014 - SEP 20, 2014

VIN (Vehicle Identification Number) Range

Begin : 19UUB3F74FA000069

End : 19UUB3F56FA000718

 Not sequential VINs**Description of Defect :**

Description of the Defect : Incorrect values for Gross Vehicle Weight Rating (GVWR), Gross Axle Weight Rating (GAWR) front and rear are specified on the safety certification label.

INCORRECT

GVWR 4762 LBS GAWR F 2502 LBS, R 2337 LBS

GVWR 2160 KG GAWR F 1135 KG, R 1060 KG

CORRECT

GVWR 4751 LBS GAWR F 2579 LBS, R 2194 LBS

GVWR 2155 KG GAWR F 1170 KG, R 995 K

Description of the Safety Risk : Non-compliance with Part 567.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

August 25, 2014

Honda of America Mfg. (HAM) began mass production of 2015 model year TLX vehicles.

Sept. 22, 2014

An incorrect certification label was discovered during a vehicle quality check at HAM. Immediate repair took place on units in factory inventory. Investigation also began to determine if affected units had been shipped to dealers.

Sept. 26, 2014

Honda Motor Company completed the investigation and determined that a noncompliance exists and a noncompliance recall will be conducted.

Description of Remedy :

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to an Acura automobile dealer. The dealer will apply a corrective label free of charge.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : SEP 27, 2014 - SEP 27, 2014

Planned Owner Notification Date : OCT 21, 2014 - OCT 21, 2014

* NR - Not Reported