

Part 573 Safety Recall Report**14V-628****Manufacturer Name :** Trans Tech Bus**Submission Date :** OCT 03,2014**NHTSA Recall No. :** 14V-628**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Trans Tech Bus

Address : 7 Lake Station Road
Warwick NY 10990

Company phone : 845-988-2333

Population :

Number of potentially involved : 188

Estimated percentage with defect : 94

Vehicle Information :

Vehicle : 2007-2014 Trans Tech Student Safety Transporter

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : School Bus

Production Dates : JAN 01, 2007 - SEP 01, 2014

VIN (Vehicle Identification Number) Range

Begin : 1GB6G6BG0E1135472

End : 1GB6G5BG3D1174825

 Not sequential VINs

Vehicle : 2008-2014 Trans Tech Student Transporter Aero

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : School Bus

Production Dates : JAN 01, 2007 - SEP 01, 2014

VIN (Vehicle Identification Number) Range

Begin : 1GB6G5BGXD1175521

End : 1GB6G5BG3D1174825

 Not sequential VINs

Vehicle : 2007-2014 Trans Tech RoadStar

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : School Bus

Production Dates : JAN 01, 2007 - SEP 01, 2014

VIN (Vehicle Identification Number) Range

Begin : 1GB6G5BG3D1174825

End : 1GB6G5BGXD1175521

 Not sequential VINs**Description of Defect :**

Description of the Defect : Platform Pivot Plate Fracture on the base platform of the Wheelchair Lift.

Description of the Safety Risk : Crack propagation leading to lift operation.

Description of the Cause : NR

Identification of Any Warning that can Occur : Fracturing and cracking along pivot plane.

Supplier Identification :**Component Manufacturer**

Name : Ricon Corporation

Address : 1135 Aviation Place

San Fernando CA 91340

Country : US

Chronology :

Trans Tech Bus was informed on Friday, September 19th, 2014 of a defect present on Ricon lifts manufactured from 2006 to 2014. There was no prior chronology or testing present on our end.

Description of Remedy :

Description of Remedy Program : All time for repairs will be reimbursed by the Ricon corporation, additionally, the repair kit is sent free of charge.

How Remedy Component Differs from Recalled Component : As this time, this information is not available.

Identify How/When Recall Condition was Corrected in Production : this is a vendor recall, it was immediately fixed for us. They had delayed shipping their product until they fixed it.

Recall Schedule :

Description of Recall Schedule : All mailings will be sent out by November 1st, 2014 depending on the response to the draft letters.

Planned Dealer Notification Date : NOV 01, 2014 - NOV 01, 2014

Planned Owner Notification Date : NOV 01, 2014 - NOV 01, 2014

* NR - Not Reported