

Part 573 Safety Recall Report**14V-642****Manufacturer Name :** Wheeled Coach Industries, Inc.**Submission Date :** OCT 08,2014**NHTSA Recall No. :** 14V-642**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Wheeled Coach Industries, Inc.

Address : 2737 N. Forsyth Road

Winter Park FL 32792

Company phone : 9999999999

Population :

Number of potentially involved : 29

Estimated percentage with defect : 90

Vehicle Information :

Vehicle : 2014-2014 Dodge Dodge 4500

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : These vehicles may possibly have the Liquid Springs Volume Mount Bracket involved in NHTSA recall E034.

Production Dates : SEP 01, 2013 - AUG 22, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 Chevy Chevy CG33803

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : See NHTSA Recall # 14E034

Production Dates : JAN 01, 2014 - JUL 24, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2013-2015 Ford F450

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : UNKNOWN

Power Train : NR

Descriptive Information : See NHTSA Recall #14E-034

Production Dates : SEP 01, 2013 - AUG 22, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : See NHTSA Recall # 14E034. LiquidSpring LLC has decided that a defect which relates to motor vehicle safety exists in a component in certain LS suspension systems installed on Ford E450, F450, F550, and GM G3500/4500 chassis, and only suspension systems for the above chassis are included in the safety recall.

Description of the Safety Risk : See NHTSA Recall # 14E034.

Description of the Cause : These suspension systems are typically installed on ambulances, shuttle buses, RV's, and other specialty vehicles. The affected system component is the fluid volume mount bracket. The bracket may develop a fracture that may result in the fluid volume becoming supported only by hose connection(s). Continued vehicle use in this fluid volume support condition [hose connection(s) only] may result in the fluid volume contacting the ground which could cause damage to the chassis and/or other vehicles, and possibly result in a crash.

Identification of Any Warning that can Occur : See NHTSA Recall # 14E034.

Supplier Identification :**Component Manufacturer**

Name : LiquidSpring LLC

Address : 3416 Rascal Drive
Lafayette IN 47909

Country : US

Chronology :

We received a NHTSA recall # 14E-034 from LiquidSpring LLC that is dated 8/14/14.

Description of Remedy :

Description of Remedy Program : If you have a Ford E450, F450, F550, GM3500/4500 chassis equipped with a LiquidSpring suspension system within the above serial number range, please contact LiquidSpring to arrange service to have the fluid volume mount brackets replaced, free of charge.

The LiquidSpring contact information is as follows:

Phone: 765-474-7816 ext. 109 8:00 a.m. – 5:00 p.m. EST

Email: warranty@liquidspring.com

How Remedy Component Differs from Recalled Component : See NHTSA Recall # 14E-034.

Identify How/When Recall Condition was Corrected in Production : See NHTSA Recall # 14E-034.

Recall Schedule :

Description of Recall Schedule : See NHTSA Recall # 14E-034. We are only sending one customer notification as a courtesy. Since this is LiquidSpring's recall, they have probably created a schedule for notification.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported