

Part 573 Safety Recall Report**14V-652****Manufacturer Name :** Keystone RV Company**Submission Date :** OCT 16,2014**NHTSA Recall No. :** 14V-652**Manufacturer Recall No. :** 14-217**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : 17400 Hackberry Drive
Goshen IN 46526

Company phone : 219-642-4590

Population :

Number of potentially involved : 1,412

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2015 Dutchmen Aerolite Travel Trailer

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 2014-2015 Dutchmen Aerolite Travel Trailers manufactured in Goshen, IN.

Production Dates : DEC 02, 2013 - SEP 11, 2014

VIN (Vehicle Identification Number) RangeBegin : 47CTAEL21EP633379 End : 47CTAET2XEP633428 Not sequential VINsBegin : 4YDT24823EP910001 End : 4YDT28224EP910251 Not sequential VINsBegin : 4YDT22523FP910056 End : 4YDT21821FP910403 Not sequential VINs

Vehicle : 2014-2015 Dutchmen Denali Travel Trailer and Fifth Wheel

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 2014-2015 Dutchmen Denali Travel Trailers and Fifth Wheels manufactured in
Goshen, IN.

Production Dates : DEC 02, 2013 - SEP 11, 2014

VIN (Vehicle Identification Number) RangeBegin : 47CFD1V27EP633347 End : 47CFD1V24EP633483 Not sequential VINsBegin : 4YDF24424EP940000 End : 4YDT26121EP940376 Not sequential VINsBegin : 4YDF26224FP940000 End : 4YDF24424FP940385 Not sequential VINs

Description of Defect :

Description of the Defect : It has been decided the wiring to the 12V breakers located by the battery may not be connected to the protected terminal of the breaker.

Description of the Safety Risk : If this condition exists it will lead to an increased risk of fire if an electrical short should occur on the unprotected circuit.

Description of the Cause : During a routine audit it was discovered the wiring was connected incorrectly.

Identification of Any Warning that can Occur : None

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : United States

Chronology :

September 15, 2014 – During a routine audit it was discovered the wiring was connected incorrectly. October 13, 2014 - After investigation into the cause of the wiring fault, it was decided to recall all vehicles from the date of a new employee hire up till the problem was discovered and corrected.

Description of Remedy :

Description of Remedy Program : The dealer will verify the wiring to the breakers is connected to the protected terminal and if not make the necessary correction. The service and parts required for this corrective action will be provided at no charge to the owner.

How Remedy Component Differs from Recalled Component : The vehicles that do not have the defect have the wiring to the breakers connected to the protected terminal.

Identify How/When Recall Condition was Corrected in Production : September 15, 2014 – During a routine audit it was discovered the wiring was connected incorrectly. All vehicles at the manufacturing facility were inspected and corrected.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the owners of the recreational vehicles by letter beginning in October 2014 pending NHTSA approval. A final copy of the owner letter will also be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : OCT 24, 2014 - OCT 24, 2014

Planned Owner Notification Date : OCT 24, 2014 - OCT 24, 2014

* NR - Not Reported