## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

14V-262

**Manufacturer Name:** Suzuki Motor of America, Inc. **NHTSA Recall No. / MFR Recall No.:** 14V-262 /XA

**Recall Subject:** Headlamp Switch or DRL Module Overheating

**Owner Notification Beginning Date:** OCT 29, 2014

**Owner Notification End Date:** 



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	JAN 26, 2016	2015-4	184,244	30,413	14,172	817
4	OCT 26, 2015	2015-3	184,244	28,713	7,646	817
3	JUL 29, 2015	2015-2	184,244	22,344	7,930	822
2	APR 30, 2015	2015-1	184,244	15,738	6,740	822
1	JAN 26, 2015	2014-4	184,244	4,685	3,020	627

This Document Last Updated: FEB 08, 2016

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.