

Part 573 Safety Recall Report**14V-131****Manufacturer Name :** Autocar Industries, LLC**Submission Date :** AUG 25,2014**NHTSA Recall No. :** 14V-131**Manufacturer Recall No. :** T-1403**Manufacturer Information :**

Manufacturer Name : Autocar Industries, LLC

Address : 551 South Washington Street

Hagerstown IN 47346

Company phone : 765-489-5499

Population :

Number of potentially involved : 11

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2014 AUTOCAR XSPOTTER

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : NR

Production Dates : NOV 23, 2009 - OCT 21, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2013-2013 AUTOCAR XSPOTTER

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : NOV 23, 2009 - OCT 21, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2012-2012 AUTOCAR XSPOTTER

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : NOV 23, 2009 - OCT 21, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2011-2011 AUTOCAR XSPOTTER

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : NOV 23, 2009 - OCT 21, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2010-2010 AUTOCAR XSPOTTER

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : NOV 23, 2009 - OCT 21, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Autocar Industries, LLC (Autocar) is recalling certain model year 2010-2014 Xspotter vehicles manufactured November 23, 2009, through October 21, 2013, and equipped with Cummins Westport Model ISL G and ISX12 G engines. Condensation in the intake manifold may freeze during cold weather conditions and interfere with the proper operation of the intake manifold pressure sensor.

Description of the Safety Risk : The improper operation of the sensor could induce elevated exhaust temperatures or flames from the exhaust pipe, increasing the risk of a vehicle fire or burn injury to a person near the exhaust pipe.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Cummins

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Cummins Inc. and Cummins Wesport Inc. will notify owners, and authorized Cummins service facilities will upload a new ECM calibration, free of charge. The recall began on April 12, 2014. Owners may contact Autocar at 1-765-489-5499 or Cummins Inc. at 1-800-343-7357. Autocar's number for this recall is T-1403.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : APR 01, 2014 - NR

* NR - Not Reported