

Part 573 Safety Recall Report**14V-261****Manufacturer Name :** General Motors LLC**Submission Date :** JAN 16,2015**NHTSA Recall No. :** 14V-261**Manufacturer Recall No. :** 14093**Manufacturer Information :**

Manufacturer Name : General Motors LLC

Address : 30001 VAN DYKE

MAIL CODE 480-210-2V WARREN MI 48090

Company phone : 999

Population :

Number of potentially involved : 218,000

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2008-2008 CHEVROLET AVEO

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

Descriptive Information : 2008 Chevrolet Aveo

Production Dates : SEP 27, 2003 - MAR 25, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2007-2007 CHEVROLET AVEO

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : NR - NR

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2004-2004 CHEVROLET AVEO

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : NR - NR

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2005-2005 CHEVROLET AVEO

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : NR - NR

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2006-2006 CHEVROLET AVEO

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : NR - NR

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : General Motors is recalling certain model year 2004-2008 Chevrolet Aveo vehicles equipped with daytime running lights (DRL). In the affected vehicles, there may be heat generated within the DRL module located in the center console in the instrument panel, which could melt the DRL module.

Description of the Safety Risk : If the DRL module melts due to the heat generation, it could cause a vehicle fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Hamsar

Address : NR

FOREIGN STATES

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Dealers will install a revised DRL module, inspect the wiring connector for heat damage, and clean the DRL circuit grounds. This service will be performed for you at no charge. Pursuant to 577.11, GM will provide reimbursement to owners for repairs according to the plan submitted on May 23, 2013. The manufacturer has not yet provided a notification schedule. Owners may contact General Motors customer service at 1-800-222-1020 (Chevrolet). General Motors recall number for this campaign is 14093.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Interim Owner Letters mailed August 14, 2014.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported