

Part 573 Safety Recall Report

14V-268

Manufacturer Name : Stoughton Trailers, LLC**Submission Date :** APR 25, 2016**NHTSA Recall No. :** 14V-268**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Stoughton Trailers, LLC

Address : 416 South Academy Street

Stoughton WI 53589-0606

Company phone : 608-873-2500

Population :

Number of potentially involved : 879

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2014-2014 STOUGHTON AHV

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : SAF Holland pivot bolt defect

Production Dates : NOV 05, 2013 - NOV 21, 2013

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2014-2014 STOUGHTON AVW

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : SAF Holland Pivot Bolt Defect

Production Dates : OCT 01, 2013 - DEC 18, 2013

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2014-2014 STOUGHTON AVXW

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : SAF Holland Pivot Bolt Defect

Production Dates : OCT 01, 2013 - DEC 16, 2013

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 4 : 2014-2014 STOUGHTON ZGPVW

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : SAF Holland Pivot Bolt Defect

Production Dates : OCT 01, 2013 - DEC 17, 2013

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Stoughton Trailers, LLC (Stoughton) is recalling certain 2014 AVW trailers manufactured October 1, 2013, through December 18, 2013, AVXW trailers manufactured December 3, 2013, through December 16, 2013, ZGPVW trailers manufactured October 1, 2013, through December 17, 2013, and AHV trailers manufactured November 5, 2013, through November 21, 2013, and equipped with certain SAF-Holland-brand CBX Trailer Suspension Air Ride Axle Systems. The affected trailer suspensions have pivot bolts that may fail.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Failure of the pivot bolts may cause the suspension and attached axle to separate from the trailer, increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : SAF-Holland

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Stoughton will notify owners, and SAF-Holland-approved repair shops will replace the defective pivot bolts with new pivot bolts, free of charge. The recall is expected to begin by late May 2016. Owners may contact Stoughton customer service at 1-608-873-2555, or SAF-Holland customer service at 1-888-396-6501.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : MAY 27, 2016 - JUN 24, 2016

* NR - Not Reported