

**Part 573 Safety Recall Report****14V-293****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** FEB 24, 2016**NHTSA Recall No. :** 14V-293**Manufacturer Recall No. :** P31**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

**Population :**

Number of potentially involved : 6,120

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2014-2014 DODGE DURANGO

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Some 2014 Jeep Grand Cherokee, Jeep Grand Cherokee SRT, Dodge Durango, and  
Jeep Cherokee vehicles

Production Dates : JAN 16, 2014 - APR 08, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 JEEP CHEROKEE

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : MAR 06, 2014 - APR 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 JEEP GRAND CHEROKEE

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : JAN 16, 2014 - APR 08, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Chrysler Group LLC (Chrysler) is recalling certain model year 2014 Dodge Durango vehicles manufactured January 16, 2014 to April 8, 2014, Jeep Grand Cherokee vehicles manufactured January 16, 2014 to April 8, 2014, Jeep Grand Cherokee SRT vehicles manufactured February 3, 2014 to April 8, 2014, and Jeep Cherokee vehicles manufactured March 6, 2014 to April 17, 2014. When the adaptive cruise control is engaged and the driver presses the accelerator pedal to increase the vehicle's speed more than the cruise control system would on its own, the vehicle may continue to accelerate briefly after the accelerator pedal is released.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The unintended continued acceleration may increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Robert Bosch LLC

Address : NR

NR

Country : NR

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Chrysler will notify owners, and dealers will re-flash the Driver Assistance System Module (DASM), free of charge. The recall began in June 2014. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is P31.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JUN 30, 2014 - NR

\* NR - Not Reported