

**Part 573 Safety Recall Report****14V-362****Manufacturer Name :** Mazda North American Operations**Submission Date :** AUG 20,2015**NHTSA Recall No. :** 14V-362**Manufacturer Recall No. :** 7714F**Manufacturer Information :**

Manufacturer Name : Mazda North American Operations

Address : 1025 Connecticut Avenue, NW

Suite 910 Washington DC 20036

Company phone : 248-295-7859

**Population :**

Number of potentially involved : 19,544

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2004-2004 MAZDA MAZDA6

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

Descriptive Information :

Production Dates : MAY 29, 2002 - MAR 04, 2004

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2003-2003 MAZDA MAZDA6

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : MAY 29, 2002 - MAR 04, 2004

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2004-2004 MAZDA RX-8

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : JUN 25, 2003 - JUN 30, 2003

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Updated on August 20,2015; the number of the affected vehicles are updated. Mazda North America Operations (Mazda) is recalling certain model year 2003-2004 Mazda6 vehicles and 2004 RX-8 vehicles to address a safety defect in the passenger side frontal air bag which may produce excessive internal pressure causing the inflator to rupture upon deployment of the air bag.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of a crash necessitating deployment of the passenger's frontal air bag, the inflator could rupture with metal fragments striking and potentially seriously injuring the passenger seat occupant or other occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Takata/TK Holdings

Address : NR

NR

Country : NR

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Owners of all vehicles on which a defective air bag may have been installed as original equipment will be notified. Dealers will replace the defective air bag inflator, free of charge. The safety recall is scheduled to begin in August 2014. Owners may contact Mazda Customer Assistance Center at 1-800-222-5500. Mazda's recall campaign number is 7714F. Note: This is an expansion of NHTSA Recall No. 13V-130.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : AUG 01, 2014 - NR

Planned Owner Notification Date : AUG 25, 2014 - NR

\* NR - Not Reported