OMB Control No.: 2127-0004

Part 573 Safety Recall Report

14V-386

Manufacturer Name: Mercedes-Benz USA, LLC.

Submission Date : OCT 01,2014 **NHTSA Recall No. :** 14V-386

Manufacturer Recall No.: 2014060005



Manufacturer Information:

Manufacturer Name : Mercedes-Benz USA, LLC.

 $Address: One\ Mercedes\ Dr,\ PO\ Box\ 350$

Montvale NJ 07645-0350 Company phone : 201-573-5339

Population:

Number of potentially involved: 311 Estimated percentage with defect: 100

☐ Not sequential VINs

Vehicle Information:

Vehicle: 2014-2014 MERCEDES BENZ SL550

Vehicle Type: LIGHT VEHICLES

Body Style : 2-DOOR Power Train : GAS

Production Dates: MAR 19, 2014 - MAY 05, 2014

VIN (Vehicle Identification Number) Range

Vehicle: 2014-2014 MERCEDES BENZ SL63

Vehicle Type : LIGHT VEHICLES Body Style : NR

Power Train: NR

Begin: NR

Descriptive Information: NR

Production Dates: MAR 19, 2014 - MAY 05, 2014

VIN (Vehicle Identification Number) Range

End: NR

Vehicle: 2014-2014 MERCEDES BENZ SL65

Vehicle Type: LIGHT VEHICLES

Body Style : NR Power Train : NR

Descriptive Information: NR

Production Dates: MAR 19, 2014 - MAY 05, 2014

Description of Defect:

Description of the Defect: Mercedes-Benz USA, LLC (Mercedes-Benz) is recalling certain model year 2014 SLK

250, SLK 350, SLK 55 AMG, SL 550, SL 63 AMG, and SL 65 AMG vehicles

manufactured March 19, 2014, through May 5, 2014. Due to an air bag assembly

error, the front passenger air bag may not deploy properly.

Description of the Safety Risk: In the event of a crash necessitating front passenger air bag deployment, the

front passenger seat airbag may not properly deploy, increasing the risk of

injury to the front passenger seat occupant.

Description of the Cause: NR

Identification of Any Warning that can Occur: NR

Supplier Identification:

Component Manufacturer

Name : Takata Address : NR

NR

Country: NR

Chronology:

NR

Description of Remedy:

Description of Remedy Program: Mercedes-Benz will notify owners, and dealers will replace the front

passenger air bag, free of charge. Parts for the remedy are not currently available. Mercedes-Benz distributed an interim letter to owners on July 17, 2014. A second owner letter will be mailed when parts are available. Owners may contact Mercedes-Benz at 1-800-367-6372. Note: Until the vehicle has been remedied, owners are advised that passengers or other

items should not be placed in the passenger seat.

How Remedy Component Differs from Recalled Component: NR

Identify How/When Recall Condition was Corrected in Production: NR

Recall Schedule:

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date: NR - NR

| Part 573 Safety Recall Report | 14V-386 | Page 4 |
|---------------------------------------|--|--------|
| | | |
| * NR - Not Reported | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| The information contained in this rep | port was submitted pursuant to 49 CFR §573 | |