



The affected pivot bolt may experience an intergranular quench crack where the bolt head meets the body of the bolt.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the bolt cracks it could fracture causing separation of the axle/suspension assembly from the trailer if both sides of the pivot connection fail, which increases the risk of a vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :**

**Component Manufacturer**

Name : SAF-Holland

Address : 1950 Industrial Blvd  
Muskegon MICHIGAN 49443-0425

Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Timpte will notify owners, and dealers will replace the old pivot bolts with new pivot bolts with a white paint dot on the head of the bolt, free of charge. The recall is expected to begin on August 20, 2014. Owners may contact Timpte customer service at 1-402-367-3056 SAF-Holland customer service at 1-888-396-6501.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : AUG 20, 2014 - NR

Planned Owner Notification Date : AUG 20, 2014 - NR

\* NR - Not Reported