

Description of the Safety Risk : If the keypad experiences corrosion due to water infiltration it could cause an electrical short, increasing the risk of a vehicle fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Jayco will notify owners, and dealers will add a 5am fuse to protect the wiring running from the house batter to the TriMark Keypad, and replace the keypad free of charge. The recall is expected to begin September 2014. Owners may contact Jayco customer service at 1-800-283-8267.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : SEP 30, 2014 - SEP 30, 2014

Planned Owner Notification Date : SEP 30, 2014 - SEP 30, 2014

* NR - Not Reported