OMB Control No.: 2127-0004

Part 573 Safety Recall Report

14V-470

Manufacturer Name: Porsche Cars North America, Inc.

Submission Date : FEB 29, 2016 **NHTSA Recall No. :** 14V-470 **Manufacturer Recall No. :** AE02



Manufacturer Information:

Manufacturer Name: Porsche Cars North America, Inc.

Address : One Porsche Drive Atlanta GA 30354

Company phone: 1-800-767-7243

Population:

Number of potentially involved: 7 Estimated percentage with defect: 100

Vehicle Information:

Vehicle: 2015-2015 PORSCHE MACAN S, MACAN TURBO

Vehicle Type: LIGHT VEHICLES

Body Style : SUV Power Train : GAS

Descriptive Information: Brake Booster

Production Dates : MAR 06, 2014 - APR 26, 2014

VIN (Vehicle Identification Number) Range

Begin: WP1AF2A51FLB90079	End: WP1AF2A51FLB90115	✓ Not sequential VINs
Begin: WP1AF2A51FLB90079	End: WP1AF2A51FLB90115	✓ Not sequential VINs
Begin: WP1AB2A52FLB50282	End: WP1AB2A50FLB52211	☐ Not sequential VINs
Begin: WP1AF2A51FLB90079	End: WP1AF2A51FLB90115	✓ Not sequential VINs
Begin: WP1AB2A52FLB50282	End: WP1AB2A50FLB52211	☐ Not sequential VINs
Begin: WP1AF2A51FLB90079	End: WP1AF2A51FLB90115	✓ Not sequential VINs
Begin: WP1AB2A52FLB50282	End: WP1AB2A50FLB52211	☐ Not sequential VINs
Begin: WP1AF2A51FLB90079	End: WP1AF2A51FLB90115	✓ Not sequential VINs
Begin: WP1AB2A52FLB50282	End: WP1AB2A50FLB52211	☐ Not sequential VINs
Begin: WP1AF2A51FLB90079	End: WP1AF2A51FLB90115	✓ Not sequential VINs
Begin: WP1AB2A52FLB50282	End: WP1AB2A50FLB52211	☐ Not sequential VINs
Begin: WP1AF2A51FLB90079	End: WP1AF2A51FLB90115	✓ Not sequential VINs
Begin: WP1AB2A52FLB50282	End: WP1AB2A50FLB52211	☐ Not sequential VINs
Begin: WP1AF2A51FLB90079	End: WP1AF2A51FLB90115	✓ Not sequential VINs
Begin: WP1AB2A52FLB50282	End: WP1AB2A50FLB52211	☐ Not sequential VINs

Page 2

Description of Defect:

Description of the Defect: Porsche Cars North America, Inc. (Porsche) is recalling certain model year 2015

Macan vehicles. The affected vehicles may have been manufactured with a damaged brake booster during installation. This could cause the vacuum in the brake

booster to drop when the brakes are actuated, resulting in reduced brake force

boost.

FMVSS 1:NR FMVSS 2:NR

Description of the Safety Risk: If the brake booster is damaged and experiences reduced braking effect, that

will increase the risk of a vehicle crash.

Description of the Cause: NR

Identification of Any Warning that can Occur: NR

Supplier Identification:

Component Manufacturer

Name: TRW Braking Systems Polska

Address: Leonarda do Vinci 7

Gliwice FOREIGN STATES 44-121

Country: Poland

Chronology:

NR

Description of Remedy:

Description of Remedy Program: Porsche will notify owners, and dealers will inspect and replace the brake

booster if necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Porsche customer service at

1-770-290-3627. Porches' number for this recall is AE02.

How Remedy Component Differs from Recalled Component: NR

Identify How/When Recall Condition was Corrected in Production: NR

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NR - NR

Part 573 Safety R	ecall Report	14V-470	Page 3
* NR - Not Reported			
The information contained in this report was submitted pursuant to 49 CFR §573			