

**Part 573 Safety Recall Report****14V-487****Manufacturer Name :** Ferrari North America, Inc.**Submission Date :** SEP 30,2014**NHTSA Recall No. :** 14V-487**Manufacturer Recall No. :** 54**Manufacturer Information :**

Manufacturer Name : Ferrari North America, Inc.

Address : 250 Sylvan Avenue  
Englewood Cliffs NJ 07632-2500

Company phone : 1800-999-9999

**Population :**

Number of potentially involved : 3,082

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2014-2014 FERRARI 458

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** The affected vehicles consist of Model Years 2010 to 2014 Ferrari 458 Italia and 458 Spider vehicles manufactured from the beginning of production (March 5, 2010) through May 20, 2013 with an assembly range from 90612 through 114448 and a VIN range from ZFF67NFA3A0173114 to ZFF68NHA5E0196796.

Production Dates : MAR 05, 2010 - MAY 20, 2013

**VIN (Vehicle Identification Number) Range**

Begin : ZFF67NFA3A0173114

End : ZFF68NHA5E0196796

 Not sequential VINs

Begin : ZFF67NFA3A0173114

End : ZFF68NHA5E0196796

 Not sequential VINs

Begin : ZFF67NFA3A0173114

End : ZFF68NHA5E0196796

 Not sequential VINs

Vehicle : 2013-2013 FERRARI 458

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : MAR 05, 2010 - MAY 20, 2013

**VIN (Vehicle Identification Number) Range**

Begin :

End :

 Not sequential VINs

Vehicle : 2010-2010 FERRARI 458

Vehicle Type : LIGHT VEHICLES



**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

As a result of Ferrari's recent determination of a noncompliance with another FMVSS (which was reported to NHTSA on July 16, 2014), Ferrari started an internal review of the compliance status of its vehicles with other FMVSSs. As a result of this review, Ferrari identified a running change that was made to the front trunk latch in May 2013. Upon further review, Ferrari determined that the vehicles manufactured prior to the running change did not comply with S4.3(b)(1)(i) of FMVSS No. 401, in that the latch system does not release the secondary latch when the vehicle is stationary. In all operating conditions, the latching system works properly to release the front trunk lid from the primary latching position.

**Description of Remedy :**

Description of Remedy Program : Ferrari will notify owners, and dealers will modify the existing front trunk latch system with a new component that will meet requirements, free of charge. Manufacturer has not yet provided a notification schedule. Owners may contact Ferrari customer service at 1-866-788-6760. Ferrari's number for this recall is 54.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : SEP 23, 2014 - SEP 23, 2014

Planned Owner Notification Date : SEP 23, 2014 - SEP 23, 2014

\* NR - Not Reported