

Part 573 Safety Recall Report**14V-677****Manufacturer Name :** Morgan Olson Corporation**Submission Date :** OCT 24,2014**NHTSA Recall No. :** 14V-677**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Morgan Olson Corporation

Address : 1801 S. Nottawa Street

Strugis MI 49091

Company phone : 616-659-0200

Population :

Number of potentially involved : 100

Estimated percentage with defect : 100

Vehicle Alterer Information :

Vehicle : 2014-2014 Sprinter 2500

Sprinter Van Upfit with GVWR of 9600 lbs and 3-tray wall mounted document

Descriptive Information : holder installed above driver's seat. Affected vehicles were sold to only one customer within the time-frame specified.

Production Dates : MAY 30, 2014 - AUG 01, 2014

Description of Defect :

Description of the Defect : An aluminum document holder was installed on the cab side of the load area partition in an area which may cause a noncompliance with FMVSS 201

Description of the Safety Risk : During a crash, an unbelted occupant may strike the document holder, resulting in high G-forces above the criteria specified in FMVSS 201

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : United States

Chronology :

A specification review for a similar vehicle on October 21, 2014 indicated there may be a non-compliance with the location of the document holder. Further discussions with the document holder manufacturer resulted in the decision to move the document holder out of caution.

Description of Remedy :

Description of Remedy Program : Morgan Olson will relocate the document holder to the load side of the vehicle partition, outside the target areas specified in FMVSS 201. In the event that any vehicles have already been modified by the customer, Morgan Olson will request an invoice from them for reimbursement.

How Remedy Component Differs from Recalled Component : The new position of the document holder is not in a location identified as a target area by FMVSS 201.

Identify How/When Recall Condition was Corrected in Production : On October 22, 2014, production personnel were informed to install the document holder on the load side of the partition. All in-process vehicles were corrected at this time.

Recall Schedule :

Description of Recall Schedule : Morgan Olson warranty personnel began visiting customer locations on October 23, 2014.

Planned Dealer Notification Date : OCT 31, 2014 - NOV 14, 2014

Planned Owner Notification Date : OCT 31, 2014 - NOV 14, 2014

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported