

Part 573 Safety Recall Report**14V-679****Manufacturer Name :** Spartan Motors, Inc.**Submission Date :** OCT 27,2014**NHTSA Recall No. :** 14V-679**Manufacturer Recall No. :** 14015**Manufacturer Information :**

Manufacturer Name : Spartan Motors, Inc.

Address : 1541 Reynolds Road

Charlotte MI 48813

Company phone : 517-543-6400

Population :

Number of potentially involved : 65

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2011-2015 Spartan Motors Chassis SB

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : UNKNOWN

Power Train : DIESEL

Descriptive Information : School bus chassis equipped with air brake systems.

Production Dates : DEC 21, 2010 - JUN 26, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : ABS harness connectors for the rear axle may be reversed.

Description of the Safety Risk : The ABS system may not detect rear wheel lock up on appropriate side of the rear axle. This could cause the wheel to lock up increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : There is no warning.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : United States

Chronology :

On July 28, 2014 Spartan Chassis received a warranty claim alleging the rear wheels locked up during a preservice DOT inspection. On August 14, 2014, Spartan Chassis began an internal investigation based on the warranty claim. During the investigation, it was determined the ABS harness could be installed incorrectly. The team assigned to review the issue assessed the risk, identified the population of affected chassis, and made the recommendation to issue a recall. On October 20, 2014, Spartan Chassis determined a safety defect may exist in the affected chassis.

Description of Remedy :

Description of Remedy Program : Spartan Motors Chassis, Inc. will authorize to have the affected chassis to be inspected and the cables installed correctly free of charge.

How Remedy Component Differs from Recalled Component : Chassis affected by this recall are equipped with air brake systems. Other SB Chassis are not.

Identify How/When Recall Condition was Corrected in Production : A stop ship was issued and chassis were inspected to confirm the ABS harness was installed correctly on, or near, August 19, 2014.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NOV 14, 2014 - NOV 14, 2014

Planned Owner Notification Date : NOV 26, 2014 - NOV 26, 2014

* NR - Not Reported