

Part 573 Safety Recall Report**14V-687****Manufacturer Name :** Eldorado National- Kansas**Submission Date :** OCT 29,2014**NHTSA Recall No. :** 14V-687**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Eldorado National- Kansas

Address : 1655 Wall Street
Salina KS 67401

Company phone : (913) 392-2171

Population :

Number of potentially involved : 2

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2013-2013 F550 Aero Elite Ford

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : LiquidSpring Volume Mount Bracket Safety Recall Notice 14E-034.

Production Dates : MAY 06, 2013 - JUN 06, 2013

VIN (Vehicle Identification Number) Range

Begin : 1FDGF5GT7DEA87748

End : 1FDGF5GT7DEA87749

 Not sequential VINs**Description of Defect :**

Description of the Defect : As reported by Liquid Spring in the NHTSA Recall Notice 14E-034 Customer Notification, it states that the Volume Mount Bracket may develop a fracture that may result in the fluid volume becoming supported only by the hose connection(s).

Description of the Safety Risk : As reported by Liquid Spring in the NHTSA Recall Notice 14E-034 Customer Notification, it states continued vehicle use in this fluid volume condition (hose connection(s) only) may result in the fluid contacting the ground which could cause damage to the chassis and/or other vehicles, and possibly resulting in a crash.

Description of the Cause : Liquid Spring in the NHTSA Recall Notice 14E-034 Customer Notification, did not make any statements regarding the cause for the fracture.

Identification of Any Warning that can Occur : Liquid Spring in the NHTSA Recall Notice 14E-034 Customer Notification, did not indicate that there were warning signs that precede or occur to the component prior to failure.

Supplier Identification :**Component Manufacturer**

Name : LiquidSpring LLC

Address : 3416 Rascal Drive

Lafayette INDIANA 47909

Country : United States

Chronology :

Liquid Spring NHTSA Recall Notice 14E-034 Customer Notification did not provide any chronology of events leading up to the defect decision.

Description of Remedy :

Description of Remedy Program : Liquid Spring NHTSA Recall Notice 14E-034 Customer Notification states that the bracket assembly should be replaced with new brackets.

LiquidSpring states that once the customer contacts LiquidSpring and verifies their vehicle is in the affected group, LiquidSpring will make arrangements to locate a local service center and cover the labor and material cost to have the fluid volume mount brackets replaced.

How Remedy Component Differs from Recalled Component : Liquid Spring NHTSA Recall Notice 14E-034 Customer Notification included Volume Mount Replacement Instructions, and drawings which indicate that the bracket face/attachment plate has been redesigned. The Volume Bracket Replacement component has been identified with a new part number by LiquidSpring LLC.

Identify How/When Recall Condition was Corrected in Production : Liquid Spring NHTSA Recall Notice 14E-034 Customer Notification provided a serial number range of the affected suspension systems. Eldorado National - Kansas will notify the Dealer and End-Customer of Record of the LiquidSpring Recall Campaign 14E-034.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NOV 07, 2014 - NOV 07, 2014

Planned Owner Notification Date : NOV 07, 2014 - NOV 07, 2014

* NR - Not Reported