

Part 573 Safety Recall Report**14V-770****Manufacturer Name :** Chrysler Group LLC**Submission Date :** DEC 10,2014**NHTSA Recall No. :** 14V-770**Manufacturer Recall No. :** P40 Expanded**Manufacturer Information :**

Manufacturer Name : Chrysler Group LLC

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 357,933

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2003-2005 Dodge Ram 1500, 2500, 3500 Pickup

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : The "DR" vehicles being recalled are those equipped with Takata "SPI" or "PSPI" front passenger airbag inflators and that were originally sold, or ever registered, in the following areas known for high absolute humidity: the states of Alabama, Florida, Georgia, Hawaii, Louisiana, Mississippi, and Texas, along with the US Territories of American Samoa, Guam, Puerto Rico, Saipan, and the U.S. Virgin Islands.

Production Dates : JUN 20, 2002 - JUL 31, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2005-2005 Dodge Ram 2500, 3500 Pickup

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : The "DH" vehicles being recalled are those equipped with Takata "PSPI" front passenger airbag inflators and that were originally sold in or ever registered in areas known for high absolute humidity: including the states of Alabama, Florida, Georgia, Hawaii, Louisiana, Mississippi, and Texas, along with the US Territories of American Samoa, Guam, Puerto Rico, Saipan, and the Virgin Islands.

Production Dates : MAY 11, 2004 - JUL 31, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2004-2005 Dodge Durango

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : The vehicles being recalled are those equipped with Takata "PSPI" front passenger airbag inflators and that were originally sold in or ever registered in areas known for high absolute humidity: including the states of Alabama, Florida, Georgia, Hawaii, Louisiana, Mississippi, and Texas, along with the US Territories of American Samoa, Guam, Puerto Rico, Saipan, and the Virgin Islands.

Production Dates : JUL 21, 2003 - JUL 31, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2005-2005 Dodge Dakota

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : The vehicles being recalled are those equipped with Takata "PSPI" front passenger airbag inflators and that were originally sold in or ever registered in areas known for high absolute humidity: including the states of Alabama, Florida, Georgia, Hawaii, Louisiana, Mississippi, and Texas, along with the US Territories of American Samoa, Guam, Puerto Rico, Saipan, and the Virgin Islands.

Production Dates : MAY 24, 2004 - JUL 31, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2005-2005 Chrysler 300, 300C, SRT8

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The vehicles being recalled are those equipped with Takata "PSPI" front passenger airbag inflators and that were originally sold in or ever registered in areas known for high absolute humidity: including the states of Alabama, Florida, Georgia, Hawaii, Louisiana, Mississippi, and Texas, along with the US Territories of American Samoa, Guam, Puerto Rico, Saipan, and the Virgin Islands.

Production Dates : JAN 07, 2004 - JUL 31, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2005-2005 Dodge Magnum

Vehicle Type : LIGHT VEHICLES

Body Style : STATIONWAGON

Power Train : GAS

Descriptive Information : The vehicles being recalled are those equipped with Takata "PSPI" front passenger airbag inflators and that were originally sold in or ever registered in areas known for high absolute humidity: including the states of Alabama, Florida, Georgia, Hawaii, Louisiana, Mississippi, and Texas, along with the US Territories of American Samoa, Guam, Puerto Rico, Saipan, and the Virgin Islands.

Production Dates : JAN 07, 2004 - JUL 31, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : Per Takata's 573 Safety Defect Information Report, certain Takata passenger inflators exposed to consistently high absolute humidity regions could be susceptible to rupture and the front passenger airbag could deploy abnormally in a crash, increasing the risk of injury to the occupant. The cause of the potential for ruptured inflators and the influence of high absolute humidity are under investigation.

Description of the Safety Risk : In the event of an airbag deployment, if the airbag inflator were to rupture metal fragments may contact the vehicle's occupant(s), resulting in an increased risk of injury.

Description of the Cause : The cause is under investigation.

Identification of Any Warning that can Occur : None.

Supplier Identification :

Component Manufacturer

Name : Takata Corporation

Address : 2500 Takata Drive

Auburn Hills MICHIGAN 48326

Country : United States

Chronology :

Please see attached supplemental information titled "Chrysler Group LLC Chronology 14V-770".

Description of Remedy :

Description of Remedy Program : • Replace the front passenger airbag inflator.

• Chrysler has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, Chrysler, as part of the owner letter, will request that customers send the original receipt

and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : Replacement inflators are of the same design and materials as the inflators being replaced, pursuant to continuous process improvements, as communicated to Chrysler by Takata.

Identify How/When Recall Condition was Corrected in Production : Unknown.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JAN 19, 2015 - JAN 19, 2015

Planned Owner Notification Date : JAN 19, 2015 - JAN 26, 2015

* NR - Not Reported