

**Part 573 Safety Recall Report****14V-822****Manufacturer Name :** Kia Motors America**Submission Date :** DEC 22,2014**NHTSA Recall No. :** 14V-822**Manufacturer Recall No. :** SC112**Manufacturer Information :**

Manufacturer Name : Kia Motors America

Address : 111 Peters Canyon Road  
Irvine CA 92606

Company phone : (949)468-4800

**Population :**

Number of potentially involved : 95,314

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2010-2013 Kia Soul

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : Headliner plates for 2010-2013MY Soul vehicles equipped with sunroof

Production Dates : JAN 08, 2009 - OCT 02, 2013

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : The 2010-2013MY Soul vehicles with sunroofs are equipped with headliner plates designed as part of the energy absorbing structure of the headliner. Under certain circumstances, the plates may detach from the headliner upon deployment of the curtain airbag.

Description of the Safety Risk : If the headliner plates become detached, an occupant may be injured.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Daehan Solution Co.

Address : 30, Namdongdae-Ro 369 Beon Gil, Namdong-  
Incheon

Country : United States

**Chronology :**

See attached document titled "SC112\_573 Notice\_Soul Headliner Chronology"

**Description of Remedy :**

Description of Remedy Program : All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Kia dealer. Kia will instruct dealers to apply industrial adhesive strips to secure the headliner plates. Kia will reimburse owners for repair expenses already incurred pursuant to Kia's General Reimbursement Plan filed April 14, 2014.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : JAN 26, 2015 - FEB 13, 2015

Planned Owner Notification Date : FEB 02, 2015 - FEB 18, 2015

\* NR - Not Reported