

**Part 573 Safety Recall Report****14V-828****Manufacturer Name :** Southeast Toyota Distributors, LLC**Submission Date :** DEC 31,2014**NHTSA Recall No. :** 14V-828**Manufacturer Recall No. :** SET-14B**Manufacturer Information :**

Manufacturer Name : Southeast Toyota Distributors, LLC

Address : 100 Jim Moran Boulevard

Deerfield Beach FL 33442

Company phone : 954-429-2000

**Population :**

Number of potentially involved : 3,924

Estimated percentage with defect : 0

**Vehicle Information :**

Vehicle : 2014-2015 Toyota 4Runner

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : This recall only applies to certain vehicles with accessories installed by Southeast Toyota Distributors, LLC which may have accessory fasteners that were under or over torqued during the installation process.

Production Dates : JUN 01, 2013 - DEC 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2015 Toyota FJ Cruiser

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : This recall only applies to certain vehicles with accessories installed by Southeast Toyota Distributors, LLC which may have accessory fasteners that were under or over torqued during the installation process.

Production Dates : JUN 01, 2013 - DEC 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2015 Toyota Land Cruiser

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : This recall only applies to certain vehicles with accessories installed by Southeast Toyota Distributors, LLC which may have accessory fasteners that were under or over torqued during the installation process.

Production Dates : JUN 01, 2013 - DEC 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2014-2015 Toyota RAV4

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : This recall only applies to certain vehicles with accessories installed by Southeast Toyota Distributors, LLC which may have accessory fasteners that were under or over torqued during the installation process.

Production Dates : JUN 01, 2013 - DEC 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2014-2015 Scion FRS

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : This recall only applies to certain vehicles with accessories installed by Southeast Toyota Distributors, LLC which may have accessory fasteners that were under or over torqued during the installation process.

Production Dates : JUN 01, 2013 - DEC 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2014-2015 Scion xB

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : This recall only applies to certain vehicles with accessories installed by Southeast Toyota Distributors, LLC which may have accessory fasteners that were under or over torqued during the installation process.

Production Dates : JUN 01, 2013 - DEC 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2014-2015 Toyota Tacoma

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : This recall only applies to certain vehicles with accessories installed by Southeast Toyota Distributors, LLC which may have accessory fasteners that were under or over torqued during the installation process.

Production Dates : JUN 01, 2013 - DEC 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

Not sequential VINs

**Description of Defect :**

Description of the Defect : During a routine audit, SET found that two accessory installers were not using a supplied torque wrench to properly attach running boards and other accessories to vehicles when the installation instructions specifically required a specific torque for the attaching fasteners. If the fasteners are not properly tightened to the specified torque, the fastener could come loose, possibly allowing the accessory to fall off the vehicle, which could result in a crash or injury.

Description of the Safety Risk : If accessory fasteners are not properly tightened to the specified torque, the fastener could come loose, possibly allowing the accessory to fall off the vehicle, which could result in a crash or injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : Occupant may or may not hear an audible warning due to fastener vibration.

**Supplier Identification :**

**Component Manufacturer**

Name : NR

Address : NR

NR

Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : All potentially affected vehicles will be recalled. Owners will receive a letter via US mail, requesting they return their vehicle to a Toyota dealer for repair. The corrective action will consist of inspecting and tightening the

affected bolts with a torque wrench pursuant to instructions specified by SET. The work will be performed at no charge to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Owner notification letters will be provided to NHTSA prior to mailing.

Planned Dealer Notification Date : DEC 23, 2014 - JAN 09, 2015

Planned Owner Notification Date : FEB 09, 2015 - FEB 13, 2015

\* NR - Not Reported