

Federal Recall Information

Bulletin #:

1213H

What's New

New safety recall for 567/579 with Allison transmissions

Section

Cab

Description

Model 567/579 Allison Shifter backlight

Release Date

02/11/2014

Introduction

Peterbilt has determined that certain model 567 and 579 with Allison transmissions built between January 13, 2013 and December 3, 2013 do not have power supplied to the gear shifter display for backlighting. Backlighting is used to aid the driver in selecting a gear in low light situations. The lack of backlighting may create a situation where it is difficult to know what gear is selected which may lead to an injury accident or property damage.

Resolution

Repair the harness to include necessary wire circuits.

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

SIR will indicate chassis involved in this recall with the designator of "1213H" in the campaign field. File quick claim 1213H

For Field...	Enter...
Failure Location	026-011-149 Shifter Harness
Failure Type	700
Claim Type	C
Campaign Number	1213H
SRT TBD	1.0 hr to add new wire and route to splice block

Parts

Parts are available through PACCAR Parts (via normal parts ordering) and reimbursed by this recall at DealerNet + 30% markup.

Qty	Part Number	Description
1	BRN2624-007	Brown 18 ga wire

Labor

Peterbilt will reimburse the dealer for 1 hours of labor to repair the harness.

Background

Procedure

See attached procedure

Attachments