

GM CUSTOMER CARE AND AFTERSALES
DCS3492
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 8, 2015

Subject: 14152E – Safety Recall
Transmission Shift Cable Fracture
Revised Service Procedure

Models: 2004-2007 Chevrolet Malibu Maxx; 2004-2008 Chevrolet Malibu;
2005-2008 Pontiac G6, 2007-2008 Saturn AURA Equipped with 4-
Speed Automatic Transmission (ME7/MN5)

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The service procedure in this bulletin has been revised to include an inspection procedure. Please discard all copies of bulletin 14152D.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES