

GM CUSTOMER CARE AND AFTERSALES
DCS3376
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 1, 2014

Subject: 14152C – Safety Recall
Transmission Shift Cable Fracture
Revised Service Procedure

Models: 2004-2007 Chevrolet Malibu Maxx; 2004-2008 Chevrolet Malibu;
2005-2008 Pontiac G6, 2007-2008 Saturn AURA Equipped with 4-
Speed Automatic Transmission (ME7/MN5)

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The Service Procedure section has been revised. A park lock cable inspection has been included in the service repair. Please discard all copies of bulletin 14152B.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES