Next Unread Message

View Message

From American Honda Parts, Service & Technical Division, Campaign Administration		
American Honda Parts, Service & Technical Division, Campaign Administration	Sent on	05 15 2014 Expires on 05 28 2014
Stop Sale/Safety Recall: 2013 Fit M/T Right Driveshaft	From	American Honda Parts, Service & Technical Division, Campaign Administration
	Subject	Stop Sale/Safety Recall: 2013 Fit M/T Right Driveshaft

DATE: May 15, 2014

TO: All Honda Sales, Service & Parts Managers and Personnel

FROM: American Honda Parts, Service & Technical Division, Campaign Administration

RE: Stop Sale/Safety Recall: 2013 Fit M/T Right Driveshaft

Today, May 15, 2014 American Honda will notify NHTSA of a **Stop Sale** order and **Safety Recall** for 1,038 2013 Fit vehicles. Any new or used vehicles in dealer stock must be repaired per S/B 14-024, *Safety Recall: Right-Side Driveshaft* prior to sale. **Refer to the eResponsibility report or VIN Inquiry status to determine which vehicles in your inventory are affected.**

Problem

A small number of right driveshafts were not properly heat treated during production. An improperly heat-treated driveshaft may form cracks, possibly leading to driveshaft breakage.

Repair

Affected vehicles require inspection of the right inboard boot band. Vehicles equipped with driveshaft boot bands with serial numbers in the affected range will require right driveshaft replacement. Of the 1,038 affected VINs, 561 will require right driveshaft replacement. Please verify an affected serial number prior to ordering a new driveshaft for replacement.

Parts

Parts are available through the controlled parts order process. A valid affected VIN will be required to place an order of a right driveshaft replacement kit, P/N 06440-TF0-305. Replaced driveshafts must be retained at your dealer for call-in by American Honda per the parts return instructions detailed in S/B 14-024.

Warranty

Warranty information is detailed in S/B 14-024, *Safety Recall: Right-Side Driveshaft*. Note that to ensure payment, claims for replaced driveshafts must include the affected boot band serial number in the DTC field section of the claim.

Service Bulletin

In support of this recall, S/B 14-024 has been posted on ISIS as of May 15, 2014. It includes inspection, repair, parts, and warranty information related to this campaign.

Customer Notification

Honda expects to complete initial customer notification by the middle of June 2014.

As always, make sure to check iN VIN Inquiry status to determine if a vehicle is eligible for this recall.

Click <u>here</u> for a copy of service bulletin 14-024.

BACK TO TOP

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.