

GM CUSTOMER CARE AND AFTERSALES
DCS4279
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 5, 2016

Subject: 14187D – Safety Recall
Front Safety Belt Anchor
Service Procedure Revised

Models: 2009-2014 Buick Enclave
2009-2014 Chevrolet Traverse
2009-2014 GMC Acadia
2009-2010 Saturn Outlook

To: All General Motors Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

This bulletin has been revised to update step 12 of the service procedure. A pull test must now be performed to ensure the connector and CPA are fully engaged. Please see the attached bulletin for details and discard all copies of bulletin 14187C.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES