

GM CUSTOMER CARE AND AFTERSALES
DCS3252
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 18, 2014

Subject: 12261B – Safety Recall
Intermittent Airbag Warning Light Illuminated – Replace Steering
Wheel Airbag Coil
Population Expanded

Models: 2012 Buick Verano, Chevrolet Camaro, Cruze, and Sonic

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

Additional population has been added to this recall. Please discard all copies of bulletin 12261A.

Customer Letter Mailing

The customer letter mailing will begin on July 25, 2014.

Global Connect (GWM)

The “Investigate Vehicle History” (IVH) screen will be updated July 18, 2014.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES