

VOLKSWAGEN DEALERSHIP COMMUNICATION

Date: July 09, 2014

To: Dealer Principal, Sales Manager, Service Manager, Parts Manager and Warranty Administrator

Subject: Safety Recall 40K9 / Stop Sale STP3

2015MY Volkswagen Golf/GTI

Front Stabilizer Links

IMPORTANT NOTICE TO DEALERS - FOR IMMEDIATE DISTRIBUTION

This is to inform you about voluntary safety recall 40K9 for the front stabilizer links on certain 2015MY Golf and GTI vehicles. This safety recall replaces stop-sale code STP3 on affected dealer inventory vehicles.

- On July 09, 2014 an initial parts allocation will be sent to dealers. While this allocation will be based
 upon the number of affected vehicles in your inventory, we ask that affected customer vehicles be
 given priority over inventory units for repair.
- On July 10, 2014, safety recall code 40K9 will be visible on all affected vehicles in Elsa, and repair instructions will be available in Elsa and ServiceNet.
- A second parts allocation will be made to dealers prior to customer notification (on or before July 22, 2014).

What should dealers do?

- The affected inventory vehicles will be identified on a dealer's VIM report with the campaign code 40K9. Only dealers with inventory vehicles affected by this action will see vehicles tagged with 40K9 on their VIM report.
- If you have an affected vehicle, <u>DO NOT</u> sell, lease, or dealer-trade it until the recall repair has been
 made. If you are using an affected vehicle as a demo, discontinue using it immediately.
- Please keep any affected vehicle in a secure area where it cannot be made available for sale, lease or trade until the recall repair has been made.

Important Reminder on Vehicles Affected by Safety and Compliance Recalls By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

If you have any questions or require additional assistance, please contact Warranty. As always, any press inquiries should be directed to Volkswagen Public Relations.

Volkswagen Product Compliance

Attachment: Campaign Data Sheet (1)



CAMPAIGN DATA SHEET

CAMPAIGN TYPE		SAFETY RECALL	
SAGA CODE		40K9 (replaces stop-sale code STP3)	
MARKET(S)		United States and Canada	
AFFECTED VEHICLES		2015 MY Volkswagen Golf/GTI	
TOPIC		Front Stabilizer Links	
PROBLEM DESCRIPTION		Due to insufficient torque performed at the factory during vehicle assembly, the stabilizer link fasteners may loosen further over time. If this happens, there will be considerable noise coming from the front of the vehicle. In rare cases, this can lead to the stabilizer link detaching and interfering with the vehicle's steering, leading to an increased steering effort. Unexpected increased handling effort may lead to a crash without warning.	
CORRECTIVE ACTION		Replace the front stabilizer links on affected vehicles.	
CUSTOMER NOTIFICATION DATE		On or about July 22, 2014	
ELSA VISIBILITY DATE		July 10, 2014	
VIM VISIBILITY DATE		July 10, 2014	
VEHICLE COUNT	TOTAL AFFECTED	USA: Approximately 2,001	CANADA: Approximately 446
	DEALER INVENTORY	USA: Approximately 705	CANADA: Approximately 108
	CPO INVENTORY	USA : 0	CANADA: 0
APPROXIMATE REPAIR TIME		Up to 50 TU	
SPECIAL TOOLS NEEDED?		SEE WORK PROCEDURE INSTRUCTIONS	
PARTS REQUIRED		YES - SEE WORK PROCEDURE INSTRUCTIONS	
COMPLETION FACTOR/REPLACEMENT RATE (TARGETED ALLOCATION INFORMATION)		Targeted Allocation not applicable to this recall	
PROJECTED DEALER RETURN BLOCK DATE		TBD	
INITIAL PARTS ALLOCATION DATE		July 09, 2014	
TECHNICIAN TRAINING REQUIRED?		SEE WORK PROCEDURE INSTRUCTIONS	
EXPIRATION DATE		NONE	
ADDITIONAL INFORMATION		Important Reminder on Vehicles Affected by Safety and Compliance Recalls: By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal/Canadian Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.	