



09/04/2014

New Safety Recall Advanced Communication – P52090414

Chrysler Group LLC (Chrysler) announced a safety recall on all 2013 and 2014 model year (ZD) Dodge Viper SRT models.

Some of the above vehicles may experience incorrect airbag deployment velocity due to an improper air gap between the Seat Track Position (STP) sensor and the seat track detection plate. Excessive air gap between the STP sensor and the detection plate could cause an incorrect sensor reading. Incorrect airbag deployment velocity, during certain crash events, could cause additional vehicle occupant injury.

Chrysler will conduct a voluntary safety recall on all involved vehicles to measure the air gap between the Seat Track Position (STP) sensor and the seat track detection plate. Seat tracks with an excessive air gap will have a shim installed onto the seat track detection plate.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
Chrysler Group LLC