

GM CUSTOMER CARE AND AFTERSALES
DCS3606
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 30, 2015

Subject: 14457C – Safety Recall
Rear Toe Link Adjuster Lock Nut Torque
Service Procedure Revised

Models: 2010-2015 Cadillac SRX and 2011-2012 Saab 9-4X

To: All Cadillac Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
Used Vehicle Sales Manager and Warranty Administrator

This bulletin has been revised to add a note in the Service Procedure section (see Step 4).

Please discard all copies of bulletin 14457B.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES