

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5551
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 22, 2020

Subject: 14457D – Safety
Rear Toe Link Adjuster Jam Nut Torque
Revised Service Procedure section

Models: 2010 – 2015 Cadillac SRX
2011 – 2012 Saab 9-4X

To: All General Motors Dealers

This bulletin has been revised to update the Service Procedure section. Toe links will only be replaced instead of inspected. Please discard all copies of bulletin 14457C.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS