



After-sales Retailer Support

Takata Front Passenger Air Bag Inflator

Voluntary Safety Recall Campaign -Regional

Update 4 – M35/45 - Final Procedure & Automatic Parts Shipment

Reference: P4235
Date: January 30, 2015

Attention: Retailer Principal, Sales, Parts and Service Managers

******* Retailer Announcement *******

On January 7th, 2015 Infiniti released an announcement which contained an **interim** repair procedure to repair affected **M35/45** vehicles. The interim procedure instructed retailers to replace the Passenger Air Bag Module Assembly.

This communication is to let retailers know that **Inflators** are now available, the final repair procedure had been developed, and an automatic parts shipment was sent to retailers in areas with affected owners.

******* What Retailers Should Do *******

1. Verify the subject vehicle is affected by this recall campaign using Service Comm **I.D. P4235**.
2. Repair affected vehicles using **ITB14-034**.
 - For M sedan, retailers are now replacing the front passenger air bag **Inflator**.
 - Parts and Claims information is included in the attached TSB.

******* Parts Information *******

An automatic parts shipment has been sent to 28 retailers in areas with affected owners. Parts shipments should arrive at retailers beginning January 31st. Should a retailer need additional inflators, use the attached order form.

MODEL	PART DESCRIPTION	PART #	ORDER FORM REQUIRED
M35/45	Passenger Air Bag Inflator	K85FA-7994D	Yes

******* Claims Information *******

CAMPAIGN ("CM) I.D.	DESCRIPTION	OP CODE	FRT
P4235	M- Replace front passenger air bag Inflator	P42353	2.7 hrs

Contact the Warranty claims call center 1-800-258-7008 Option 7, for rental pre-approval as necessary.