

**From:** [Broadcast Messaging System](#)  
**To:** [DL-BMS Message Monitors](#)  
**Subject:** Delivery Stop - Model Year 2014 I12 (i8) - Fuel Tank  
**Date:** Monday, October 20, 2014 2:46:09 PM

Publish Date: October 20, 2014  
From: Technical Service  
Expiration Date: November 03, 2014

DCSnet Message  
**Urgent**



**Subject: Delivery Stop - Model Year 2014 I12 (i8) - Fuel Tank**

A Delivery Stop has been issued on certain Model Year 2014 BMW I12 (i8) vehicles. The bolt for attaching a ground cable at the bottom of the fuel tank may not be welded correctly, which could result in a fuel tank failure. Although, the actual failure rate is extremely low, every i8 vehicle in your inventory should be inspected prior to delivery. A Service Information bulletin (B16 14 14), which includes details of a fuel tank inspection, will be published shortly.

Affected vehicles have been identified in the Vehicle Comment section of the DCS vehicle history.

Thank you.

Attachments:  
No Attachments No Attachments

Recipients: BMW Passenger Cars, CC-RegionalTechEngineers  
BMW Passenger Cars, CC-AreaManagers  
BMW Passenger Cars, CC-AfterSalesAreaManagers  
BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, Warranty Administrator

