



Aftersales Retailer Support

2012-2015 Infiniti QX56/QX80

Fuel Pressure Sensor

Update #8 – Warranty Claims Filing Extension

Reference: R1417
Date: May 7, 2015

Attention: Retailer Principal, Sales, Parts and Service Managers

******* Retailer Announcement *******

On April 22, Infiniti announced that the final repair procedure for **QX56/QX80**. Infiniti also informed retailers that new claims coding was available for the final repair, which no longer required the removal of the intake manifold to torque the fuel pressure sensor. Infiniti agreed to honor the claims coding for the old repair method, using intake manifold gaskets, through May 6th, 2015.

Infiniti is now extending the intake manifold claims filing period for one additional week to enable retailers to sell down their inventory of intake manifold gaskets.

- New Claims coding is published with the final QX56/QX80 repair procedure. Retailers can begin using this new claims coding immediately. Infiniti will honor the claims coding for the old repair method using intake manifold gaskets through May 13th, 2015.

Model	Description	Op Code/ Part Number	FRT / QTY
QX56/QX80	Re-torque Fuel Rail Pressure Sensor	R14177	1.0 hrs.
	Manifold Gasket	14035-1LA0A	8
	Throttle Body Gasket	16175-1LA0A	1
<i>Claims coding expires after May 13, 2015</i>			

- QX56/QX80 repair orders opened on May 14th, 2015 or later will not be allowed to claim the intake manifold gasket repair method. Retailers must use claims coding provided in **ITB15-017**.

******* Retailer Communication *******

Beginning May 7th, 2015, retailers can find a copy of this announcement on NNA.net.com under My Documents in three locations:

- Parts>Campaigns>
- Sales>Campaigns>
- Service>Campaigns>
 - **R1417**