



419 W. Pike St., Jackson Center, OH 45334

## **IMPORTANT SAFETY RECALL**

**Airstream Interstate Motorhome**

**NHTSA Recall Number 14V-  
Transport Canada Recall Number 2014-**

**Date:**

**TO: Airstream Dealer**

### **Problem**

Airstream has decided that certain Airstream recreational vehicles were built with power inlets whose terminal lugs were not properly torqued down on the incoming power wires. If the wires are loose, arcing may occur causing a rise in heat which may result in the melting of the power inlet or if hot enough, a fire.

### **RANGE OF VEHICLES INVOLVED:**

- 2014 and 2015 Airstream Travel Trailers

### **WARRANTY REIMBURSEMENT:**

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is 30 minutes.

### **SERVICE ACTION:**

Inspect and repair the power inlet per Airstream Warranty Instructions.

encl. – Owners Letter

**Dave Schumann**

Director of Service and Warranty Administration

Re: NHTSA Recall No. 14V-  
Transport Canada Recall No. 2014-