M52 01 14

Page 1 of 1
October 2014
Technical Service

SUBJECT

Seats

Delivery Stop: Seat Backrest Adjustment

<u>MODEL</u>

F56 (Cooper, Cooper S)

SITUATION

A Delivery Stop has been issued on certain F56 vehicles produced from August 12, 2014 through September 2, 2014. These vehicles may have a malfunction in the seat backrest adjustment.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be repaired prior to dealer delivery.

This bulletin will be updated with instructions and warranty information when parts and the procedure become available. Please contact your field representatives if you have any questions.

Affected vehicles can be identified with a "Vehicle Comment" in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

Defect Code 0052600100, Delivery Stop, Seat Backrest Adjustment, see SI B52 01 14.