



TO: Parts Managers/Service Managers
FROM: Subaru of America, Inc.
DEPARTMENT: Parts & Service
DATE: 11/02/17
SUBJ: Parts Return Request – Takata Inflator 98279AE00A

Parts Return Requested for Takata Inflator Part Number 98279AE00A, 98271AE05AML, & 98271AE05AML

Takata part number 98279AE00A has been superseded by part number 98279AE04A as a recall replacement part for the 2003-2004 Legacy/Outback & 2003-2006 Baja. **Please refer to Product Campaign Bulletin TKA-16&17, TKB-16&17, & TKC-16&17, WQR-53 & WQP-51.** SOA is requesting that all retailers return existing stock of part number 98279AE00A, 98271AE05AML, & 98271AE05AML to their facing RDC.

All claims were entered for the retailers based on their PRIME inventory. Please contact your RDC Admin or the PICs with any discrepancies in the claim quantity.

Please Note: All Takata recall parts must be ordered through PRIME.

IMPORTANT: Airbag inflators are considered a HAZMAT material and must be shipped following the appropriate HAZMAT shipping process (refer to Subarunet > Parts Policies/Procedure Manual > Section 14 Parts Returns > 14.1 Returns of Hazardous Materials).