



A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

IMPORTANT SAFETY RECALL

February 12, 2014

VIN: 3BKBH27X5BF281691
Alabama Gas Corporation
605 Richard Arrington Jr Blvd N
Birmingham, AL 35203-2707

Subject: SAFETY RECALL# 14KWA NHTSA (14V-008)
T440 Starter Interlock
EXPIRATION DATE: NONE VIN: 3BKBH27X5BF281691

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Kenworth has decided that a defect which relates to motor vehicle safety exists in certain model year 2011 through 2014 T440 vehicles built between March 10, 2010 and September 23, 2013. The subject chassis were manufactured with an engine and transmission harness that is incorrectly installed. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

On certain T440 vehicles equipped with Allison transmissions and Cummins Westport ISL-G engines, the neutral start interlock may be rendered inoperable due to the incorrect installation of the engine and transmission harnesses. If the engine harness is installed incorrectly, the truck may be able to be started with the transmission in gear, increasing the risk of a crash.

<i>The problem is...</i>	Engine and transmission wiring harness not connected
<i>What your dealer will do...</i>	Connect starter interlock harness
<i>What you must do ...</i>	Contact your dealer immediately to schedule an appointment

Kenworth has initiated a recall to connect your starter interlock harness. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This repair should take approximately two hours, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Quality Services Manager



A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

IMPORTANT SAFETY RECALL

February 12, 2014

VIN: 3BKBL20X3BF295548
Indiana Dept of Transportation
100 N Senate Ave Rm N755
Indianapolis, IN 46204-2216

Subject: SAFETY RECALL# 14KWA NHTSA (14V-008)
T440 Starter Interlock
EXPIRATION DATE: NONE VIN: 3BKBL20X3BF295548

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Kenworth has decided that a defect which relates to motor vehicle safety exists in certain model year 2011 through 2014 T440 vehicles built between March 10, 2010 and September 23, 2013. The subject chassis were manufactured with an engine and transmission harness that is incorrectly installed. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

On certain T440 vehicles equipped with Allison transmissions and Cummins Westport ISL-G engines, the neutral start interlock may be rendered inoperable due to the incorrect installation of the engine and transmission harnesses. If the engine harness is installed incorrectly, the truck may be able to be started with the transmission in gear, increasing the risk of a crash.

<i>The problem is...</i>	Engine and transmission wiring harness not connected
<i>What your dealer will do...</i>	Connect starter interlock harness
<i>What you must do ...</i>	Contact your dealer immediately to schedule an appointment

Kenworth has initiated a recall to connect your starter interlock harness. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This repair should take approximately two hours, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Quality Services Manager



A **PACCAR** COMPANY

Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000
(425) 828-5000

IMPORTANT SAFETY RECALL

February 12, 2014

VIN: 3BKBL20X3BF295551
Indiana Dept of Transportation
100 N Senate Ave Rm N755
Indianapolis, IN 46204-2216

Subject: SAFETY RECALL# 14KWA NHTSA (14V-008)
T440 Starter Interlock
EXPIRATION DATE: NONE VIN: 3BKBL20X3BF295551

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Kenworth has decided that a defect which relates to motor vehicle safety exists in certain model year 2011 through 2014 T440 vehicles built between March 10, 2010 and September 23, 2013. The subject chassis were manufactured with an engine and transmission harness that is incorrectly installed. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

On certain T440 vehicles equipped with Allison transmissions and Cummins Westport ISL-G engines, the neutral start interlock may be rendered inoperable due to the incorrect installation of the engine and transmission harnesses. If the engine harness is installed incorrectly, the truck may be able to be started with the transmission in gear, increasing the risk of a crash.

<i>The problem is...</i>	Engine and transmission wiring harness not connected
<i>What your dealer will do...</i>	Connect starter interlock harness
<i>What you must do ...</i>	Contact your dealer immediately to schedule an appointment

Kenworth has initiated a recall to connect your starter interlock harness. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This repair should take approximately two hours, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Quality Services Manager