


NHTSA SAFETY RECALL NUMBER 14V-646

	<b>IMPORTANT SAFETY RECALL</b>
<b>First Notice</b> <b>TR620 Pintle Ring Mount Plate Replacement Kit (VFK00-0500)</b>	

December 19, 2014

VIA USPS CERTIFIED/REGISTERED MAIL

Dear TR620 Owner:

<b>Model:</b>	<b>TR620</b>
This notice applies to your vehicle,	
<b>Serial No:</b>	

*This notice is sent to you in accordance with the requirements of the U.S. National Traffic and Motor Vehicle Safety Act.*

Vermeer has decided that a defect, that relates to motor vehicle safety, exists in certain model year 2014-2015 Vermeer TR620.

**PINTLE RING MOUNTING BOLTS MAY LOOSEN**

The pintle ring mounting plate was manufactured with incorrect steel. The pintle ring attachment bolts may loosen due to insufficient torque capacity.

**DEATH OR SERIOUS INJURY POSSIBLE**

If the pintle ring mounting bolts loosen, a loss of vehicle control may result while towing on a public highway. **Death or serious injury is possible.** Property damage is also possible.

**IMMEDIATE MACHINE MODIFICATIONS REQUIRED**

VFK00-0500 has been created to provide the necessary parts and instructions to replace the pintle ring mounting plate. **This kit must be installed as soon as possible.**

**Please contact** your authorized, independent **Vermeer dealer** immediately to arrange a mutually acceptable time and location to install VFK00-0500 **at no cost** to you for labor or materials. The installation of this kit is estimated at 8 hours of labor. If the Vermeer dealer travels to the unit to install the kit, costs may be incurred by the owner. **You must have your machine upgraded for these safety features.**

<b>Contact your local Vermeer Dealer:</b>	
	RDO VERMEER LLC - PORTLAND
	7640 NE 33RD DR
	PORTLAND OR 97211
	UNITED STATES
<b>Telephone:</b>	503-282-0694

According to our records, you currently own a Vermeer TR620 Trommel Screen. The Model and Serial Number of the TR620 is shown at the top right of this letter. If you no longer own this unit, please notify the Product Safety Department at:

Toll Free: 800-829-0051, extension 7060

Telephone: 641-621-7060

E-mail: [productsafety@vermeer.com](mailto:productsafety@vermeer.com)

If possible, please provide the name and address of the new owner.

We regret any inconvenience that these corrective measures may cause you. The required work is for the safety of the towing vehicle occupants and other drivers and passengers travelling on the public roadways. We hope that you agree that the safety benefits surpass the inconvenience.

Very truly yours,

**PRODUCT SAFETY DEPARTMENT**

*Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.*

If the authorized dealer has failed or is unable to remedy the defect without charge and within a reasonable time, contact Vermeer Product Safety by email at [productsafety@vermeer.com](mailto:productsafety@vermeer.com) or by calling 800-829-0051 or 641-621-7060. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, D.C. 20590 or call the Vehicle Safety Hotline at 888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>