




Harley-Davidson Motor Company, 3700 West Juneau Ave., PO Box 653, Milwaukee, WI 53201 414/342-4680

*****AUTO**3-DIGIT 530 P1 C1 ##



IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN # 1HD1 

Date 01/22/2015

Harley-Davidson Recall No. 0164

NHTSA Recall No.14V-794

Dear Harley-Davidson Motorcycle Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Harley-Davidson Motor Company, Inc. has decided that a defect which relates to motor vehicle safety exists in certain model year 2012 Dyna FXDF and FXDF103 model motorcycles. We are notifying you because our records indicate that you own one of the affected motorcycles.

What is the Issue?

On some of these motorcycles, the front brake master cylinder may experience corrosion in the threads for the brake line banjo bolt. If this condition remains undetected, it could result in a sudden loss of brake fluid, which could lead to a loss of front brake function, possibly resulting in a crash.

What Should You Do?

Please contact your authorized Harley-Davidson motorcycle dealer immediately and arrange an appointment to have your motorcycle repaired. Your dealer will confirm that your motorcycle is covered by this recall. If covered, the dealer will flush and inspect the front brake master cylinder and if necessary, replace the master cylinder with the master cylinder recall kit at no cost to you. The repair will take less than two hours to perform. However, due to scheduling, the dealer may require your motorcycle for a longer period of time. To verify that the service has been completed, your dealer will ask you to sign a recall claim.