


4

3

2

1

REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED



NOTE:
 REMOVE TWIST IN SEAT BELT BEFORE FASTENING END.

LEFT SIDE OF DRIVERS SEAT SHOWN
 RIGHT SIDE PASSENGER SEAT THE SAME.

A BUSHING 16620 IS ALSO INSTALLED ON THE
 OPPOSITE SIDE LINK.

REFERENCE NHSTA RECALL # 14E015.

This drawing is the property
 of Villa International all
 rights reserved.

VILLA INTERNATIONAL				
ISS LINK ASSEMBLY, RECALL FIX				
jgm 4.18.14	SIZE	FSOM NO.	DWG NO.	REV
	SCALE		03	

4

3

2

1