

**** TECHNICAL INFORMATION NOTICE ****

DATE: October 28, 2014

TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, Service Managers, and Parts Managers


RE: Parts Identification for SR14009 – 4B1 Engine Drive Belt Detachment Safety Recall

TIN NO. TIN-14-SR-009-B

AFFECTED VEHICLES: Certain 2008-2011 Lancer, Lancer Evolution, Outlander, 2009-2011 Lancer Sportback, and 2011 Outlander Sport vehicles built September 26, 2006 – June 22, 2011

PURPOSE

To assist dealerships in identifying the correct part number(s) to be used and claimed for this recall, please reference the photos and chart below:



| Vehicle | Drive Belt Part No. | | | Auto Tensioner Part No.* | | Idler Pulley Part No.* | |
|--|---------------------|----------|----------|--------------------------|----------|------------------------|----------|
| | 4451A114 | 1340A123 | 4451A115 | 1345A079 | 1345A052 | 1341A005 | 1341A029 |
| | NA - HPS | NA - EPS | TC | NA | TC | NA | TC |
| 2008-10 Lancer (2.0L & 2.4L) | X | | | X | | X | |
| 2011 Lancer (2.0L) | | X | | X | | X | |
| 2011 Lancer (2.4L) | X | | | X | | X | |
| 2009-10 Lancer Sportback (2.0L & 2.4L) | X | | | X | | X | |
| 2011 Lancer Sportback (2.0L) | | X | | X | | X | |
| 2011 Lancer Sportback (2.4L) | X | | | X | | X | |
| 2009-11 Lancer & Lancer Sportback Ralliart | | | X | | X | | X |
| 2008-11 Lancer Evolution | | | X | | X | | X |
| 2008-11 Outlander (2.4L) | X | | | X | | X | |
| 2011 Outlander Sport | | X | | X | | X | |

*If Required

NA = Normally Aspirated TC = Turbocharged HPS = Hydraulic Power Steering EPS = Electronic Power Steering