

**Toyota Motor Engineering &  
Manufacturing North America, Inc.**

Vehicle Safety & Compliance  
Liaison Office  
Mail Code: S-104  
19001 South Western Avenue  
Torrance, CA 90501

December 17, 2014

## DEFECT INFORMATION REPORT

This supplements Toyota's Part573 Report of September 29, 2014 concerning the rear leaf spring issue on certain Toyota Tacoma vehicles

The affected vehicle VIN range, corresponding number of affected vehicles, and corrective repair action is revised as noted below:

### Identification of Affected Vehicles:

Make/ Car Line	Model Year	Manufac- turer	VIN		Production Period
			VDS	VIS	
Toyota/ Tacoma	2005 - 2011	TMMBC, TMMCA, TMMTX	*U**N	5M001025 - BM113656 5Z001003 - AZ749134 BX001004 - BX006731	September 14, 2004 through December 6, 2010
			*X**N	5Z001181 - AZ749126 BX001008 - BX003266	

Note: (1) Although the involved vehicles are within the above VIN range, not all vehicles in this range were sold in the U.S.

(2) Only Pre-Runner and 4x4 vehicles in the above range are involved. Although the other Tacoma models use the same leaf spring assemblies, they are located below the rear axle instead of above it; therefore, the problem described below does not occur. No other Toyota or Lexus vehicles use the same leaf spring assembly as the subject vehicles.

Total Number of Vehicles Involved: 710,711

### Description of Corrective Repair Action:

All known owners of the subject vehicles will be notified by first class mail. Toyota dealers will replace the rear leaf spring assemblies with improved ones.