

**Toyota Motor Engineering &
Manufacturing North America, Inc.**

Vehicle Safety & Compliance
Liaison Office
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

February 3, 2015

DEFECT INFORMATION REPORT

This supplements Toyota's Part573 Report of November 26, 2014 concerning the assist grip issue on certain Toyota Sienna vehicles.

The affected vehicle VIN range and the number of the involved vehicles are revised as noted below:

Identification of Affected Vehicles:

Make/ Car Line	Model Year	Manufac- turer	VIN		Production Period
			VDS	VIS	
Toyota/ Sienna	2015	TMMI	#K3DC	FS094184 – FS096027 FS522745 – FS556298	September 2, 2014 through November 25, 2014

- Note: (1) Although the involved vehicles are within the above VIN range, not all vehicles in this range were sold in the U.S.
- (2) Certain MY15 Camry, MY15 Tundra, and MY15 Avalon use the same assist grip; however due to differences in the design of parts in the roof rail area, the force applied to the assist grip in the event of a collision that results in the deployment of a curtain airbag is not sufficient enough to cause the assist grip to completely detach.

Total Number of Vehicles Potentially Involved:

25,551