



February 26, 2014

Two whom it may concern:

It has come to our attention that a safety recall on the swing door module (model 3230 PC Board). It has the potential of overheating and causing a short circuit. This module is located on your door header of your swing doors (see attached pic). We are notifying all bus owners that have the possibility of having this issue. See attached for procedures on how to identify and get a replacement module. This recall applies to Tiffany E450 and F550 limo/shuttle busses only.

(Remove header cover, some are vinyl some carpet)



*Screws are up 2" from bottom  
2" in from left and 4" in from*



(Module is held down with double sided tape)

23129  
Ca.92570 951-  
951-443-3431fax

Cajalco rd. Perris,  
657-2680 office

*Module is held in place by double side tape.*