

June 14, 2016

00407-01886 Version 10

Safety Recall: Front Passenger's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure To High Absolute Humidity

This bulletin is replaced by S/B 16-047, Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized (Phase 1)

If you did Service Bulletin 14-070 on or before June 13, 2016. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

- **For 2002-04 CR-Vs only:** If you did the repair in this S/B on or before December 19, 2015 (RO date), use the Warranty Claim Information provided below. Any repairs after December 19, 2015, refer to S/B 15-067, *Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized*.
- **The Accord and Civic warranty information is included in case you opened an RO on or before June 14, 2015.** Refer to S/B 15-041 for any repairs made after that date.

Replacing the front passenger's airbag inflator

| Year/Model | Operation Number | Replacement Part number | Flat Rate Time | Defect Code | Symptom Code | Template ID | Failed Part Number |
|----------------------|------------------|-------------------------|----------------|-------------|--------------|-------------|--------------------|
| 2003 Accord | 7541B0 | 04785-SDA-307 | 0.7 hr | 5KN00 | JL800 | 14-070Z | 06780-SDN-A90ZA |
| | | 04790-SDA-308 | 0.7 hr | 5KN00 | JL800 | 14-070Y | 06780-SDN-A90ZA |
| 2004-05 Accord | 7541B0 | 04785-SDA-306 | 0.7 hr | 5KN00 | JL800 | 14-070X | 06780-SDN-A90ZA |
| 2001-05 Civic | 7541B0 | 04785-S5A-307 | 0.7 hr | 5KN00 | JL900 | 14-070W | 06780-S5A-A80ZA |
| 2001-04 Civic GX | | 04790-S5A-308 | 0.7 hr | 5KN00 | JL900 | 14-070V | 06780-S5A-A80ZA |
| 2003-05 Civic Hybrid | | | | | | | |
| 2002-04 CR-V | 7541B0 | 04785-S9A-307 | 0.7 hr | 5KN00 | JM000 | 14-070U | 06780-S9A-A80ZA |
| | | 04790-S9A-308 | 0.7 hr | 5KN00 | JM000 | 14-070T | 06780-S9A-A80ZA |
| 2005 CR-V | 7541B0 | 04785-S9A-306 | 0.7 hr | 5KN00 | JM000 | 24-070A | 06780-S9A-A80ZA |
| | | 04790-S9A-305 | 0.7 hr | 5KN00 | JM000 | 24-070B | 06780-S9A-A80ZA |
| | | 04790-S9A-315 | 0.7 hr | 5KN00 | JM000 | 24-070C | 06780-S9A-A80ZA |

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

| | | | | | | | |
|--------------------|--------|---------------|--------|-------|-------|---------|-----------------|
| 2003–04 Element | 7541B0 | 04785-SCV-307 | 0.8 hr | 5KN00 | JM100 | 24-070D | 06780-SCV-A80ZA |
| | | 04790-SCV-308 | 0.8 hr | 5KN00 | JM100 | 24-070E | 06780-SCV-A80ZA |
| | | 04790-SCV-318 | 0.8 hr | 5KN00 | JM100 | 24-070F | 06780-S9A-A80ZA |
| 2002 Odyssey | 7541B1 | 04785-S0X-307 | 0.7 hr | 5WX00 | JM200 | 24-070G | 06780-S0X-A70ZA |
| | | 04790-S0X-308 | 0.7 hr | 5WX00 | JM200 | 24-070H | 06780-S0X-A70ZA |
| | | 04790-S0X-318 | 0.7 hr | 5WX00 | JM200 | 24-070I | 06780-S9A-A80ZA |
| 2003–04 Odyssey | 7541B1 | 04785-S0X-306 | 0.7 hr | 5WX00 | JM200 | 24-070J | 06780-S0X-A70ZA |
| | | 04790-S0X-305 | 0.7 hr | 5WX00 | JM200 | 24-070K | 06780-S0X-A70ZA |
| | | 04790-S0X-315 | 0.7 hr | 5WX00 | JM200 | 24-070L | 06780-S9A-A80ZA |
| 2003–04 Pilot | 7541B1 | 04785-S9V-307 | 0.8 hr | 5WX00 | JM300 | 24-070M | 06780-S9V-A81ZC |
| | | 04790-S9V-308 | 0.8 hr | 5WX00 | JM300 | 24-070N | 06780-S9V-A81ZC |
| | | 04790-S9V-318 | 0.8 hr | 5WX00 | JM300 | 24-070P | 06780-S9V-A81ZC |
| 2005 Pilot | 7541B1 | 04785-S9V-306 | 0.8 hr | 5WX00 | JM300 | 24-070Q | 06780-S9V-A81ZC |
| | | 04790-S9V-305 | 0.8 hr | 5WX00 | JM300 | 24-070R | 06780-S9V-A81ZC |
| | | 04790-S9V-315 | 0.8 hr | 5WX00 | JM300 | 24-070S | 06780-S9V-A81ZC |
| 2006 Ridgeline | 7541B1 | 04785-SJC-307 | 0.7 hr | 5WX00 | JM400 | 24-070T | 77820-SJC-A00ZA |
| | | 04790-SJC-308 | 0.7 hr | 5WX00 | JM400 | 24-070U | 77820-SJC-A00ZA |
| | | 04790-SJC-318 | 0.7 hr | 5WX00 | JM400 | 24-070V | 77820-SJC-A00ZA |

Skill Level: Repair Technician