

June 14, 2016

00406-01910 Version 7

Safety Recall: Front Passenger’s Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure To High Absolute Humidity

This bulletin is replaced by S/B 16-028, Safety Recall: Front Passenger’s Airbag Inflator Can Be Over-Pressurized (Phase 1)

If you did Service Bulletin 14-044 on or before June 13, 2016. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

Replacing the front passenger’s airbag inflator

Year/Model	Operation Number	Replacement Part number	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2003–05 MDX	7541B0	04785-S3V-306	0.7 hr	5KN00	JM500	14-044N	06780-S3V-A10ZA
		04790-S3V-305	0.7 hr	5KN00	JM500	24-044N	06780-S3V-A10ZA
		04790-S3V-315	0.7 hr	5KN00	JM500	34-044N	06780-S3V-A10ZA
2005 RL	7541B0	04785-SJA-306	0.8 hr	5KN00	JM600	14-044P	06780-SJA-A80
		04790-SJA-305	0.8 hr	5KN00	JM600	24-044P	06780-SJA-A80
		04790-SJA-315	0.8 hr	5KN00	JM600	34-044P	06780-SJA-A80

Skill Level: Repair Technician

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.