



Oct 3rd, 2017

SUZUKI MOTOR OF AMERICA, INC.

IMPORTANT SAFETY RECALL - SIGNIFICANT RISK OF FIRE

This notice applies to your vehicle:

Vin# <<VIN>>

|| I M B | R C O | E ||

<<ENDORSEMENTLINE>>

<<FULLNAME>>

<<ADDRESSLINE1>> <<ADDRESSLINE2>>

<<CITYSTATEZIPCODE>>



XA-XC

<<SORTPO-
SITION>>
<<BREAKMARK>>

<<DLR1_NAME>>

<<ADDR1>>

<<1_CITY>>, <<1_STATE>> <<1_ZIP>>

<<DLR1_PHONE>>

<<DLR2_NAME>>

<<DLR2_ADDR1>>

<<2_CITY>>, <<2_STATE>> <<2_ZIP>>

<<DLR2_PHONE>>

Dear Suzuki Owner:

Suzuki Motor Corporation has decided that a defect which relates to motor vehicle safety exists in certain 2004-2008 Suzuki Forenza, 2005-2008 Suzuki Reno, and 2004-2006 Suzuki Verona vehicles.

Affected vehicles may generate heat in the Headlamp Switch and/or DRL Module, located on or near the left side of the steering column or under the instrument panel, which could melt the switch or module.

Symptoms you could experience with your vehicle related to this Safety Recall Campaign are:

- Abnormal operation of the high or low beam headlamps
- Abnormal operation of the Daytime Running Lamps
- Headlamps may be on or flashing even with vehicle parked and ignition off
- Unusual odor of overheated plastic or wiring insulation
- Intermittent vehicle battery discharge while the vehicle is sitting

If the heat generated within the Headlamp Switch or DRL Module melts the component, there is a significant risk of a fire.

There is always battery power supplied to the Headlamp Switch and DRL Module, even when the key is removed from the ignition.

Fires have been reported even in vehicles that are parked with the key removed from the ignition.

DO NOT PARK THE VEHICLE NEAR PERMANENT STRUCTURES OR IN A GARAGE UNTIL RECALL REPAIRS ARE PERFORMED.

Repair instructions have been sent to your Suzuki Service Provider and replacement parts are available to correct this condition. Your authorized Suzuki Service Provider will repair your vehicle **free of charge**.

Please contact your authorized Suzuki Service Provider to schedule an appointment to have these components replaced. Please call as soon as you receive this important Safety Recall Notification letter and mention Recall Identification Code "XA" for Forenzas and Renos, and "XC" for Veronas.

Your two nearest Suzuki Service Providers are listed above. If you need additional assistance locating a Service Provider, please call our Customer Relations Department at (714) 572-1490.

We sincerely regret any inconvenience that this recall may cause, but we are certain you understand our interest in maintaining your and your passengers' safety and your continued satisfaction with your Suzuki vehicle.

Sincerely,
SUZUKI MOTOR OF AMERICA, INC.