

U.S. Department of Transportation

National Highway Traffic Safety Administration

February 6, 2015

Mr. John Kobylarz Automotive Safety Office Jaguar Land Rover North America, LLC 555 MacArthur Boulevard Mahwah, NJ 07430

Subject: Incorrect Routing of Brake Vacuum Hose

Dear Mr. Kobylarz:

This letter serves to acknowledge Jaguar Land Rover North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

NVS-215SM

15V-042

Makes/Models/Model Years:

LAND ROVER/RANGE ROVER/2013-2014 LAND ROVER/RANGE ROVER SPORT/2014

Mfr's Report Date: January 26, 2015

NHTSA Campaign Number: 15V-042

Components:

SERVICE BRAKES, HYDRAULIC:POWER ASSIST:VACUUM:HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 24,679

Problem Description:

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain model year 2013-2014 Land Rover Range Rover vehicles manufactured August 16, 2012, to January 8, 2014, and 2014 Land Rover Range Rover Sport vehicles manufactured May 7, 2013, to January 8, 2014. In the affected vehicles, the brake vacuum hose may have been incorrectly routed allowing a hole to be worn ito it.

Consequence:

If a hole is worn into the brake vacuum hose, a complete loss of braking assistance could occur, lengthening the distance required to stop the vehicle and increasing the risk of a crash.

Remedy:

Land Rover will notify owners, and dealers will inspect the brake vacuum hose and correctly route it, as necessary, free of charge. Any brake vacuum hose that is damaged will be replaced, free of charge. The recall is expected to begin March 13, 2015. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is P052.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

